



Release Notes – Video Insight 7.1.2

Maintenance Release

OVERVIEW

This document contains information regarding our latest development update with IP Server 7.1.2 and VI MonitorPlus 7.1.2. Clients using 7.1.1 are recommended to upgrade to 7.1.2.

Changes include Optex Redscan integration, new camera integrations and high priority bug fixes regarding PTZ pan features for Panasonic WV-SF448/438. Check with your system administrator for upgrade details.

VI MonitorPlus: Recommended System Requirements

IP Server Version	VI MonitorPlus requires IP Server 7.0 or higher. VI Monitor users are able to connect to an upgraded server. VI Monitor is compatible with Version 7.0 Server, but Panasonic recommends using VI MonitorPlus.	
	VI Monitor	VI MonitorPlus
IP Server V 6.X or prior	Compatible	Not Compatible
IP Server V 7.X or higher	Compatible <i>(not recommended)</i>	Compatible
Processor/CPU	6th Generation or better Intel Core processor (3.1 GHz quad-core+)	
Memory	8GB+	
Network	1 Gb/s+	
Screen Resolution	1920 X 1080	

VI MonitorPlus Improvements

- Performance improvements
- General bug fixes

Camera Integrations

Manufacturer	Model	Features
Hikvision (New Camera)	DS-2CD2132	H264 Video Capture Dual Streaming Motion Detection VCA Show Clock Set Resolution Set Compression Set Framerate Flip Web Client JPEG
Advidia (New Camera)	E-47-V	H265 and H264 Video Capture Dual Streaming Motion Detection VCA Audio Capture Show Clock Set Codec Set Resolution Set Compression Set Framerate Flip 1x DI Capture 1x DO Trigger AUX Auto-Focus Web Client JPEG Auto-Discovery Zero License
OPTEX (New Laser Scanner)	RLS-2020i RLS-2020s	VCA 1x DI Capture 3x DO Trigger Auto-Discovery
Advantech (New IO Module)	ADAM-6050-CE	12x DI Capture 6x DO Trigger Auto-Discovery