

Release Notes – IP Server 5.5.42

OVERVIEW

This page contains information regarding our latest development update with IP Server 5.5.42 available for download on July 2, 2015.

New Camera Integrations

| Version Added | Manufacturer | Model | Features |
|---------------|--------------|---|---|
| 5.5.42 | Advidia | A-55 | Bug Fix : Web Client JPEG feature |
| 5.5.42 | IQeye | IQeye D61 IQeye D62 IQeye D63 IQeye D65 | H264 and JPEG Video Capture Audio Capture Motion Detection VCA Camera Logging Show Clock Set Codec Set Resolution Set Compression Set FPS Flip 1x DI Capture 1x DO Trigger Web Client Jpeg Auto-Discovery |
| 5.5.42 | IQeye | IQeye M61 IQeye M62 IQeye M63 IQeye M65 IQeye8712 | H264 and JPEG Video Capture Audio Capture Motion Detection VCA Camera Logging Show Clock Set Codec Set Resolution Set Compression Set FPS Flip 1x DI Capture 1x DO Trigger Web Client Jpeg Auto-Discovery AUX Auto-Focus |
| 5.5.42 | JVC | VN-H557 | H264 and JPEG Video Capture Audio Capture Motion Detection Camera Log Set Codec Set Resolution Set Compression |

| | | | |
|--------|--|--|---|
| | | | Set FPS 2x DI Capture 2x DO Trigger Pan/Tilt/Zoom Preset Set/Recall/Delete Web Client JPEG Auto-Discovery AUX Auto-Focus |
| 5.5.42 | Panasonic (Removed Support) | WV-SC397 WV-SC397A | Removed support for Panasonic WV-SC397, and Panasonic WV-SC397A. |
| 5.5.42 | Advidia | B-51 | H264 and JPEG Video Capture Audio Capture Two-Way Audio Motion Detection Camera Logging Show Clock Set Codec Set Resolution Set Compression Set FPS Flip 1x DI Capture 1x DO Capture AUX Auto-Focus Web Client JPEG Auto-Discovery Zero License |
| 5.5.42 | IPS | IPS-332 | H264 Video Capture Audio Capture Motion Detection Camera Logging Show Clock Set Resolution Set Compression Set FPS Pan/Tilt/Zoom/Focus/Iris Preset Set/Recall/Delete |
| 5.5.42 | IQeye | IQeye D55 | Resolved an issue that prevented users from connecting to an IP Camera if the camera was configured as an IQeye D55. Users may now connect to IP Cameras configured as IQeye D55s. A work-around for users without this update is to configure the IP Camera as an IQeye D53. |
| 5.5.42 | Panasonic | BB-SP104W BL-VP101 BL-VP104 BL-VP104W | H264 and JPEG Video Capture Audio Capture Motion Detection Camera Logging Show Clock Set Resolution Set Compression |

| | | | |
|--------|-------------------------|--|--|
| | | | Set FPS Flip Web Client JPEG Auto-Discovery Panasonic License |
| 5.5.42 | Panasonic | BL-VT164 BL-VT164W | H264 and JPEG Video Capture Audio Capture Motion Detection Camera Logging Show Clock Set Resolution Set Compression Set FPS Flip 3x DI Capture 1x DO Trigger Pan/Tilt/Zoom/Focus/Iris Preset Set/Recall/Delete Web Client JPEG Auto-Discovery Panasonic License |
| 5.5.42 | Dahua (Bug Fix) | DAHUA PTZ CAMERAS AND OEMS | Fixed an issue that caused Dahua cameras to Pan and Tilt at the lowest possible speed. Now the cameras should Pan and Tilt at the configured speed. |
| 5.5.42 | Fine | CDB-HD280 | H264, MPEG4, and JPEG Video Capture Audio Capture Motion Detection Camera Log Set Resolution Set Compression Set FPS Flip 1xDI Capture 1xDO Trigger Web Client JPEG |
| 5.5.42 | Winic (New Encoders) | W-HCVR7204 W-HCVR7208 W-HCVR7416 | H264 and JPEG Video Capture Audio Capture Motion Detection Camera Log Set Codec Set Compression Set FPS 1x DI Capture Pan/Tilt/Zoom/Focus/Iris Preset Set/Recall/Delete Web Client JPEG |